PreView® Has Your Blind Spot Covered

VEHICLE TYPE: SERVICE TRUCK


proudly developed by




- Reduce Blind Spot Accidents
- ► Actively Detect Objects
- ► Easily Installed

The display unit provides an audible and visual warning to the operator when an object or pedestrian is in the blind spot. This gives the driver extra time to react to prevent an accident.

One WorkZone PreView® sensor is mounted on the rear-center of the service truck. This will detect objects approximately the width of the vehicle and extend 10 feet/3 meters from the bumper of the service truck (see diagram).





Available Options: Replace in-cab display with



the PreView Plus camera and monitor. The driver will receive an audible alert when an item is in the blind zone and indicators are imposed on the monitor giving the

driver approximate ranging information.



www.aps-supply.com

DIMENSIONS

Sensor Unit: $9.25"(w) \times 1.60"(d) \times 4.36"(h)$

In-Cab Display: 2.3" (w) \times 2" (d) \times 1"(h)

NOTE: Fleet version avail. with audible only

SUGGESTED CONFIGURATION

SUGGESTED: WorkZone PreView (10')

OPTION: Replace display with camera interface, or integrate existing camera system with PreView VideoLink.

SPECIFICATIONS

Op. Temps: $-40^{\circ} - +185^{\circ}F / -40^{\circ} - +85^{\circ}C$

Current Draw: < 1/2 AMP

To determine the best configuration to fit your specific vehicle and site conditions, please call 08 9248 4419, visit www.aps-supply.com, or email sales.apsa@aps-supply.com to speak to a Blind Spot specialist.